

Tabelle1

Marke	Nummer	Ankauf
	<b>04.04.24</b>	
BMW	M ohne Nr Arvin Lamda hinten je Seite	<b>173,14 €</b>
BMW	0413050 KBA17041 103R000291 DPF	<b>57,10 €</b>
BMW	0418187 KBA17081 Typ0003 DPF	<b>70,49 €</b>
BMW	1317623 M	<b>60,34 €</b>
BMW	1317624 M	<b>60,43 €</b>
BMW	1404415	<b>174,29 €</b>
BMW	1404417	<b>197,28 €</b>
BMW	1406803 M Boysen 448541 je Seite	<b>308,38 €</b>
BMW	1406804 M Boysen je Seite	<b>300,59 €</b>
BMW	1714879 VE4991290002 HE4991530002	<b>121,13 €</b>
BMW	1714880 VE4991290002 HE4991530002	<b>124,77 €</b>
BMW	1732273	<b>88,24 €</b>
BMW	1732952	<b>110,34 €</b>
BMW	1732954	<b>108,28 €</b>
BMW	1740183 VE4473021800 HE 4473271900	<b>136,48 €</b>
BMW	1740184 VE4473021800 HE 4473271900	<b>137,09 €</b>
BMW/Alpina	1810914 Boysen	<b>139,71 €</b>
BMW	<b>4A0F</b> 454 8633378 <b>SAMPLE</b>	<b>23,63 €</b>
BMW	<b>5A29</b> BD6 2056807232	<b>70,45 €</b>
BMW	7502136D EU4	<b>61,45 €</b>
BMW	7502137C	<b>65,70 €</b>
BMW	7502222	<b>112,95 €</b>
BMW	7502223	<b>83,74 €</b>
BMW	7502226	<b>104,64 €</b>
BMW	7502227	<b>81,65 €</b>
BMW	7504019	<b>52,79 €</b>
BMW	7504067 031821E	<b>42,82 €</b>
BMW	7504068 031821E	<b>52,99 €</b>
BMW	7506569 beide zusammen	<b>62,64 €</b>
BMW	7510377	<b>86,12 €</b>
BMW	7510378	<b>79,24 €</b>
BMW	7514241-02 Mini	<b>19,33 €</b>
BMW	7516730	<b>54,87 €</b>
BMW	7516731	<b>55,82 €</b>
BMW	7516732	<b>43,08 €</b>
BMW	7516736	<b>48,14 €</b>
BMW	7516737 4041060015	<b>61,96 €</b>
BMW	7516738 4041060015	<b>54,50 €</b>
BMW	7523407 02 Mini	<b>8,92 €</b>
BMW	7523408 02 Mini	<b>9,71 €</b>
BMW	7524146 02 Mini	<b>1,02 €</b>
BMW	7527788 02 Mini	<b>17,87 €</b>
BMW	7780102 je Seite	<b>20,09 €</b>
BMW	7798329 7799596 Vorkat zu DPF Ebersp	<b>75,67 €</b>
BMW	7799595 7796710 Vorkat zu DPF Ebersp	<b>94,22 €</b>
BMW	7799596 7797208 Vorkat zu DPF Ebersp	<b>76,12 €</b>
BMW	7803728 7805250 Vorkat zu DPF Ebersp	<b>126,23 €</b>
BMW	7805568 7806501 Vorkat zu DPF Ebersp	<b>139,38 €</b>
BMW	7805568 7805271 Vorkat zu DPF Ebersp	<b>172,51 €</b>
BMW	7805569 7805572 Vorkat zu DPF Ebersp	<b>114,71 €</b>
BMW	7812877 7806502 Vorkat zu DPF Boysen	<b>106,09 €</b>

Tabelle1

BMW	7835222 5-05330.01 Boysen M	<b>51,03 €</b>
BMW	7848041 7848042 Eberspächer	<b>107,59 €</b>
BMW	7848044 7848042 Eberspächer	<b>107,59 €</b>
BMW	8088819	<b>104,54 €</b>
BMW	8090333 7848042 Eberspächer	<b>107,90 €</b>
BMW	8090334 7848042 Eberspächer	<b>107,90 €</b>
Chevrolet	96438480 JX	<b>70,23 €</b>
Chevrolet	96629315 CJ	<b>66,10 €</b>
Chevrolet	96946889 CY	<b>45,59 €</b>
Chrysler	208ACW	<b>43,74 €</b>
Chrysler	209W	<b>19,00 €</b>
Chrysler	290AAW	<b>63,52 €</b>
Chrysler	357AAA	<b>11,71 €</b>
Chrysler	797A	<b>96,01 €</b>
Chrysler	4695458 83808	<b>25,21 €</b>
Dodge	unbek. Sehr groß Rohr ca 15cm dick Diesel	<b>105,61 €</b>
Fiat	1321531080	<b>6,87 €</b>
Fiat	1351878 4913 ECOCAT Iveco Vorkat	<b>48,84 €</b>
Fiat	1914720121 beide zus. Alfa Romeo	<b>31,46 €</b>
Fiat	2035150374 Iveco Vorkat	<b>32,65 €</b>
Fiat	4012190003 baugl. ZSM	<b>78,27 €</b>
Fiat	46475795 A595 Kemira	<b>68,58 €</b>
Fiat	46540325 Kemira	<b>72,00 €</b>
Fiat	46782055 A600 HKJS10	<b>40,13 €</b>
Fiat	46794000 55185920F A600 OBC18	<b>30,16 €</b>
Fiat	46805958 3A A600 beide zusammen	<b>89,87 €</b>
Fiat	46808744 HBMT	<b>98,19 €</b>
Fiat	46808744 HRMT	<b>100,91 €</b>
Fiat	46824686 73503132	<b>152,16 €</b>
Fiat	55185920 46794000/1 A595	<b>31,58 €</b>
Fiat	55185975 46794000/1 A595	<b>31,66 €</b>
Fiat	55187600 51797393	<b>47,75 €</b>
Fiat	55187620 51797395	<b>47,31 €</b>
Fiat	55187620 51832338	<b>52,85 €</b>
Fiat	55191650 55183774 A595	<b>27,95 €</b>
Fiat	55192190 51774044 A600 FGP	<b>56,08 €</b>
Fiat	55192490 55183774	<b>29,62 €</b>
Fiat	55194436 51780170 6C-20	<b>38,53 €</b>
Fiat	55195359 51797397	<b>46,68 €</b>
Fiat	55198993 51762984	<b>28,58 €</b>
Fiat	60669656 60669657	<b>48,72 €</b>
Fiat	60669657 73201140 0602	<b>52,32 €</b>
Fiat	84287 ECOCAT T178 0905009	<b>46,03 €</b>
Fiat	84942 E1012503 Iveco ECOCAT Vorkat	<b>47,02 €</b>
Fiat	909221E	<b>138,83 €</b>
Fiat	ZSM009	<b>40,04 €</b>
Fiat	ZSM016	<b>39,17 €</b>
Fiat	ZSM041	<b>39,87 €</b>
Fiat	ZSM048	<b>40,70 €</b>
Ford	1282035B 4Krümmer lang	<b>20,58 €</b>
Ford	XM21-5E212-BA Vorkat 4-Punkt	<b>64,61 €</b>
Honda	Civic 2Rille Vorkat Diesel N43 C0...	<b>41,13 €</b>

Tabelle1

Honda	Civic 4Rille Vorkat Diesel N43	<b>34,07 €</b>
Honda	CR-V 2,2D oben 2 Monolithen	<b>74,40 €</b>
Honda	CR-V 2,2D unten 2 Monolithen	<b>87,08 €</b>
Honda	Jazz N43 F00189 Teilblech	<b>27,12 €</b>
Honda	Vorkat DPF N43	<b>71,20 €</b>
Honda	N452 12624906	<b>5,16 €</b>
Honda	Diesel Krümmer ab Turbo	<b>85,71 €</b>
Iveco	93822948 Kemira 1083-1	<b>0,00 €</b>
Jaguar	Vorkat X300 beide zus ohne Nummer	<b>37,12 €</b>
Lada	11194-1203008	<b>13,78 €</b>
Lada	21101-1203008-10	<b>36,12 €</b>
Lamborghini	07L251718 99012008 Arvin	<b>234,82 €</b>
Mazda	KL86 Guss 3er Krümmer	<b>4,87 €</b>
McLaren	14HA044CP 14HA005CP 14HA011CP Vorkat	<b>85,70 €</b>
McLaren	14HA044CP 14HA005CP 14HA011CP Nachkat	<b>23,76 €</b>
McLaren	22HA005GP 14HA005CP 14HA011CP Vorkat	<b>78,08 €</b>
McLaren	22HA005GP 14HA005CP 14HA011CP Nachkat	<b>24,51 €</b>
McLaren	unbek mclaren vorn	<b>46,11 €</b>
McLaren	unbek mclaren hinten	<b>26,17 €</b>
Mercedes	1974900914 TRIX9 HWF Testkat	<b>19,83 €</b>
Mercedes	A1904910014	<b>21,73 €</b>
Mercedes	KT0006 A2014902614	<b>5,37 €</b>
Mercedes	KT0007 A124490XX14	<b>11,60 €</b>
Mercedes	KT0019 1244903314 Nachkat zu Kat	<b>15,01 €</b>
Mercedes	KT0035 Nachkat zu Kat	<b>13,51 €</b>
Mercedes	KTA018 A2304900014 je Stück	<b>119,03 €</b>
Mercedes	KTA018 A2304901114 je Stück	<b>119,03 €</b>
Mercedes	KTA036 AMG A2044903314 beide zus.	<b>49,61 €</b>
Mercedes	PN0001 103R-000270 KBA17042 nur DPF	<b>0,00 €</b>
Mercedes	PN0003 103R-000272 KBA17044	<b>23,72 €</b>
Mercedes	PN0004 103R-000274 KBA17045	<b>114,58 €</b>
Mitsubishi	4X	<b>67,78 €</b>
Mitsubishi	SV	<b>89,14 €</b>
Nissan	1NCRP Nachkat vom GTR	<b>9,02 €</b>
Nissan	B35090 Nachkat Blech weiss geschraubt	<b>37,27 €</b>
Nissan	CC2XB Murano V6 90grad	<b>70,56 €</b>
Opel	25128543 AC Made in USA Senator	<b>46,07 €</b>
Opel	90423140 SIGRO-FINNKAT 80224	<b>87,34 €</b>
Opel	91144829 Kemira 80601	<b>36,46 €</b>
Opel	GM07 Kemira 80466 90410401 Senator	<b>67,99 €</b>
Opel	GM13 80580	<b>53,38 €</b>
Opel	GM21 90502548 90502549 80739 K3	<b>78,05 €</b>
Opel	GM23 90531170 90531171	<b>94,66 €</b>
Opel	GM43 F7 12572028	<b>33,84 €</b>
Opel	GM48 2443653	<b>10,99 €</b>
Opel	GM49 24456833 Kemira 81760 K5	<b>53,85 €</b>
Opel	GM50 24456834 Kemira 81761 K5	<b>51,67 €</b>
Opel	GM51	<b>55,39 €</b>
Opel	GM52 90424104 82098 Kemira	<b>80,59 €</b>
Opel	GM53 244438228 244438227 81895	<b>20,48 €</b>
Opel	GM54 Kemira	<b>53,07 €</b>
Opel	GM62 13101349 Bosal Manicat	<b>19,50 €</b>
Opel	GM63 24461730 Kemira	<b>47,15 €</b>

Tabelle1

Opel	GM91 55353855 Kemira 83257	<b>55,31 €</b>
Opel	GM92 95352819 Kemira 83258	<b>75,41 €</b>
Opel	GM94 55187620	<b>49,86 €</b>
Opel	GM95 55354248	<b>57,11 €</b>
Opel	GM111 12792821	<b>26,43 €</b>
Opel	GM122 55559192 Ecocat 84481	<b>55,49 €</b>
Opel	GM123 55560022 ECOCAT 84497	<b>89,58 €</b>
Opel	GM124 55559629, 55559630	<b>45,47 €</b>
Opel	GM125 55559633	<b>50,43 €</b>
Opel	GM131 55561283	<b>53,76 €</b>
Opel	GM200 55564446	<b>49,54 €</b>
PSA/Suzuki	8673	<b>55,88 €</b>
PSA	8687 Sevel Wimetal	<b>72,26 €</b>
PSA	K074	<b>6,29 €</b>
PSA	K264 WIMETAL	<b>143,67 €</b>
Renault	8200686159	<b>118,13 €</b>
Rover	KAT017 LKC000230 / 250	<b>20,13 €</b>
Rover	KAT037 1321035	<b>36,12 €</b>
Rover	ohne Nummer Vorkat 4Krümmer	<b>17,55 €</b>
Saab	4225736	<b>71,70 €</b>
Saab	4444204	<b>77,64 €</b>
Saab	4445433	<b>99,88 €</b>
Saab	4526372	<b>72,61 €</b>
Saab	4526872	<b>64,13 €</b>
Saab	4623104	<b>73,41 €</b>
Saab	4878682	<b>57,60 €</b>
Saab	4965885	<b>67,37 €</b>
Smart	KBA17096 103R-000346 DPF	<b>19,89 €</b>
Smart	PN0002 A1614900921	<b>42,04 €</b>
Subaru	OPCFE1 2Y07	<b>25,76 €</b>
Toyota	KBA17056 103R-000305 Filter	<b>0,00 €</b>
Toyota	M09	<b>29,43 €</b>
Toyota	P01	<b>74,61 €</b>
Toyota	P05	<b>75,49 €</b>
Toyota	R02 Blech LWR	<b>56,16 €</b>
Toyota	Y01	<b>13,83 €</b>
Volvo	09202731 E5528... 5Krümmer	<b>94,19 €</b>
Volvo	Vorkat 2Rippen mit Lamda	<b>67,04 €</b>
Volvo	Vorkat 2Rippen ohne Lamda	<b>17,09 €</b>
Volvo	Vorkat Gold 1 Rohr 30862751	<b>39,21 €</b>
Volvo	Vorkat Gold 2er Rohr	<b>52,01 €</b>
Volvo	30751550 beide zusammen	<b>68,22 €</b>
Volvo	31293464 Vorkat DPF	<b>79,41 €</b>
Volvo	31293899 Vorkat DPF	<b>76,41 €</b>
Volvo	31422369 Vorkat DPF	<b>78,60 €</b>
Volvo	31439684 Vorkat DPF	<b>85,62 €</b>
Volvo	31439704 Vorkat DPF	<b>77,13 €</b>
Volvo	31460823 Vorkat DPF	<b>56,76 €</b>
Volvo	9189238 Vorkat	<b>44,48 €</b>
Volvo	9207600 Vorkat	<b>35,24 €</b>
Volvo	9486407 Vorkat	<b>24,94 €</b>
VW	023131701AD T4 VR6	<b>171,33 €</b>
VW	023131701R T4 VR6	<b>76,62 €</b>

Tabelle1

VW	030178AA Rohrkat	9,42 €
VW	030178BAF	18,80 €
VW	030178CAD	21,95 €
VW	036178AA Rohrkat	7,93 €
VW	036178BAT	31,61 €
VW	036178BAK	38,78 €
VW	036178BBAD	32,42 €
VW	036178CA	8,33 €
VW	036178EAAA	23,12 €
VW	06A178AAB	3,67 €
VW	06F166AA 06F253031AC beide zus.	49,98 €
VW	06F166AA 06F253031AD beide zus.	62,33 €
VW	06F166AA 06F253031G beide zus.	64,47 €
VW	1H0131701BB	70,19 €
VW	1H0131701BJ	52,64 €
VW	1H0131701BK	55,59 €
VW	1H0131701N Eberspächer	83,65 €
VW	1H0131701Q VR6	94,43 €
VW	1H0131701P 16V	63,22 €
VW	1H1131701 Naht mitte beide zusammen	82,63 €
VW	1H1131701 ohne Naht , beide zusammen	92,84 €
VW	1J0131701FF 1J0178GA beide zus.	160,50 €
VW	1J0131701FL 1J0178GA beide zus.	106,11 €
VW	1J0178BAAK	42,86 €
VW	1J0178BAAH	130,30 €
VW	1J0178BACF	67,73 €
VW	1J0178BBAH	139,76 €
VW	1J0178CAAF	58,67 €
VW	1J0178CAAG	64,51 €
VW	1J0178CBCD	100,53 €
VW	1J0178CBDE	105,35 €
VW	1J0178CBFP	116,52 €
VW	1J0178FBFD	113,51 €
VW	1J0178LAGE	149,66 €
VW	1J1178CA 8N0254400B beide zus.	134,20 €
VW	1J1178CA 8N0131701F beide zus.	115,88 €
VW	1J1131701D 1J1178CA beide zus.	139,60 €
VW	1J1131701E 1J1178BA beide zus.	157,09 €
VW	1J1131701J 1J1178DA beide zus.	162,45 €
VW	1K0131690EA Vorkat zu DPF	33,97 €
VW	1K0131690ES D-1K0DJ Vorkat zu DPF	38,28 €
VW	1K0131701K 1K0178EA	69,16 €
VW	1K0131705DH 1K0166EA DPF komplett	68,50 €
VW	1K0131723F 1K0181DA	0,00 €
VW	3A0131701B beide zusammen	60,94 €
VW	3B0131701AB 3B0178BA	64,62 €
VW	3B0131701AB 3B0178EA	69,33 €
VW	3B0131701AB 3B0178AE	50,89 €
VW	3B0131701AD 3B0178FA	100,85 €
VW	3B0131702BA 3B0178DA	63,26 €
VW	3B7131701J 3B7178AA	71,60 €
VW	3B7131701K 3B7178AA	73,47 €
VW	3B7131701L 3B7178AA	70,61 €

Tabelle1

VW	3B7131701M 3B7178AA	<b>70,20 €</b>
VW	3D0131690AJ 3D0178HA	<b>46,87 €</b>
VW	3D0131690AL 3D0178KA	<b>46,19 €</b>
VW	3D0131690BA 3D0166DA	<b>29,00 €</b>
VW	3D0131690BB 3D0166DA	<b>28,19 €</b>
VW	3D0131690Q 3D0166DA	<b>60,80 €</b>
VW	3D0131690R 3D0166DA	<b>61,92 €</b>
VW	3D0131690AK 3D0178JA	<b>36,27 €</b>
VW	3D0131690AM 3D0178LA	<b>34,45 €</b>
VW	3W0178AA Boysen 9-0545742/43	<b>119,76 €</b>
VW	3W0253059B 3W0166CA Bentley	<b>93,43 €</b>
VW	3W0253059C 3W0166DA Bentley	<b>95,42 €</b>
VW	4B3131701AP 4B3178AA	<b>43,30 €</b>
VW	4B3131701AQ 4B3178S	<b>74,70 €</b>
VW	4B3131701AR 4B3178AB	<b>36,34 €</b>
VW	4B3131701AS 4B3178T	<b>74,28 €</b>
VW	4D4131701 4D4000178D 4D4118A	<b>69,20 €</b>
VW	4D4131701AA 4D4000178E 4D4118A 4D425321	<b>69,91 €</b>
VW	4F0131701CT 4F0000178AF	<b>45,25 €</b>
VW	4F0131701DA 4F0178AG	<b>93,04 €</b>
VW	4F0131701DH 4F0178AF	<b>48,17 €</b>
VW	4F0131701DJ 4F0178AG	<b>93,11 €</b>
VW	4G0178FA 059131705CT	<b>198,04 €</b>
VW	4G0254202K 82171307 Vorkat zu DPF	<b>209,11 €</b>
VW	4H0178FA 057131705AG Vorkat zu DPF	<b>104,38 €</b>
VW	4H0254200R	<b>108,94 €</b>
VW	4S0251211D 4S0178AA Lamborghini	<b>196,70 €</b>
VW	4S0251212D 4S0178BA Lamborghini	<b>195,81 €</b>
VW	535131701D	<b>95,68 €</b>
VW	535131701H	<b>107,03 €</b>
VW	5Q0131705AJ Vorkat zu DPF	<b>111,37 €</b>
VW	5Q0131705AQ Vorkat zu DPF	<b>112,43 €</b>
VW	5Q0131705BG Vorkat zu DPF	<b>117,62 €</b>
VW	5Q0131705G Vorkat zu DPF	<b>97,65 €</b>
VW	5Q0131705GE Vorkat zu DPF	<b>97,15 €</b>
VW	5Q0131705M 04L131645AA Vorkat zu DPF	<b>64,39 €</b>
VW	6C0166DA 04B131657D Vorkat zu DPF	<b>58,88 €</b>
VW	6K0131701M ST3 Spain	<b>46,87 €</b>
VW	6N0131701BN	<b>93,83 €</b>
VW	6N0131701BQ 6N0178FA 6N0253023C	<b>101,50 €</b>
VW	6R0131723G 6R0181AA Vorkat zu DPF	<b>36,53 €</b>
VW	6R0131690F 6R0166AA Vorkat zu DPF	<b>36,18 €</b>
VW	7H0131701A 7H0178AA Vorkat	<b>28,61 €</b>
VW	7H0131701B 7H0178BA	<b>84,79 €</b>
VW	7L0131690E 7L0166AA	<b>49,44 €</b>
VW	7L0131690F 7L0166AA	<b>49,44 €</b>
VW	7L0131690G 7L0166JA 7L0254301F	<b>65,59 €</b>
VW	7L0131701A 7L0178BA	<b>122,04 €</b>
VW	7L5254300G Porsche	<b>38,42 €</b>
VW	7L5254350E 2228085 107 Porsche	<b>39,01 €</b>
VW	7L5254350G Porsche	<b>37,17 €</b>
VW	7L5254400K Porsche	<b>84,78 €</b>
VW	7L5254450D Porsche	<b>83,88 €</b>

Tabelle1

VW	7L5254450M Porsche	<b>79,34 €</b>
VW	7L6131701J 7L6178CA	<b>55,38 €</b>
VW	7L6131701K 7L6178CA	<b>54,51 €</b>
VW	7M0131701AA 95VW-5E212-DC AE Port	<b>114,09 €</b>
VW	7M0131701S 95VW-5E212-FB AE Port	<b>80,35 €</b>
VW	7M3131701L 7M3178AA Portugal	<b>78,72 €</b>
VW	7M3131701Q 7M3178AA Portugal	<b>92,31 €</b>
VW	7M3131701R 7M3178BA 7M21-5E212-BB	<b>118,48 €</b>
VW	7M3131701S 7M3178BA YM21-5E212-DE	<b>128,02 €</b>
VW	7M3178FA 7M3181BA KBA17024	<b>44,48 €</b>
VW	8D0178BD 8D0131702GK 8D0131701EB	<b>125,05 €</b>
VW	8D0131701BP 8D0178R	<b>14,46 €</b>
VW	8D0131701BQ 8D0178AB	<b>12,94 €</b>
VW	8D0131701EB 8D0131702HA 8D0178BD	<b>111,36 €</b>
VW	8D0131701DG 9D0178BH	<b>91,63 €</b>
VW	8D0131701DK 8D0178AH LAT	<b>41,77 €</b>
VW	8D0131701DL 8D0178AJ LAT	<b>33,37 €</b>
VW	8D0131701DN 8D0178AP LAT	<b>33,90 €</b>
VW	8D0131701DM 8D0178AN LAT	<b>39,96 €</b>
VW	8D0131701FE 4B0178AA	<b>47,84 €</b>
VW	8D0131701FH 4B0178T	<b>50,28 €</b>
VW	8D0131702HH 8D0178BJ	<b>128,98 €</b>
VW	8D0131702HN 8D0178BE	<b>59,43 €</b>
VW	8D0131702HP 8D0178BE	<b>90,17 €</b>
VW	8E0131701DS 8E0178S	<b>123,09 €</b>
VW	8E0131701DT 8E0178R	<b>105,20 €</b>
VW	8E0131701GB 8E0178DJ	<b>66,82 €</b>
VW	8E0131701GC 8E0178DJ	<b>65,28 €</b>
VW	8E0131701GA 8E0178DG	<b>39,48 €</b>
VW	8E0131701FT 8E0178DG	<b>36,99 €</b>
VW	8E0131702AH 8E0178E	<b>87,31 €</b>
VW	8E0131702BH 8E0178E	<b>82,90 €</b>
VW	8E0131702BQ 8E0178BB	<b>87,18 €</b>
VW	8E0131723G 8E0181D	<b>0,00 €</b>
VW	8E0254200 3B0178DA	<b>85,55 €</b>
VW	8E0254200A 8E0178CR	<b>76,19 €</b>
VW	8E0254200E 8E0178CQ	<b>62,80 €</b>
VW	8J0131701B 8J0178AA	<b>45,17 €</b>
VW	8G0178 112029167000	<b>131,84 €</b>
VW	8L9131701D 1J0178GA beide zus.	<b>145,93 €</b>
VW	94411108112 944/3-1 Porsche	<b>115,26 €</b>
VW	96411321316 964/4-3 Porsche	<b>58,59 €</b>
VW	97011334905 Nachkat	<b>59,23 €</b>
VW	97011335005 Nachkat	<b>61,65 €</b>
VW	97011334923 Nachkat	<b>63,16 €</b>
VW	97011335024 Nachkat	<b>63,66 €</b>
VW	99311321338 993/13 Porsche beide zus.	<b>89,54 €</b>
VW	99611302152 966/05 Porsche	<b>55,83 €</b>
VW	99611302158 49816852-029 Porsche	<b>82,67 €</b>
VW	99611302254 996/02 Porsche	<b>91,96 €</b>
VW	99611302504 Porsche Lamda hinten	<b>71,99 €</b>
VW	99611302604 Porsche Lamda hinten	<b>69,21 €</b>
VW	99711303302 Porsche	<b>71,53 €</b>

Tabelle1

VW	99711303404 997`04 Porsche	<b>87,44 €</b>
VW	D-1J0AP	<b>35,22 €</b>
VW	D-1K0M	<b>31,38 €</b>
VW	J-1K0F	<b>28,25 €</b>
HJS	GB34 103R-000048	<b>43,32 €</b>
HJS	K13/1 KBA16267	<b>6,23 €</b>
HJS	K348 103R-000038	<b>57,76 €</b>
HJS	Tuning E5554690-05	<b>46,95 €</b>
HJS LKW	Scheibe HJS 11076	<b>243,27 €</b>
HJS LKW	Scheibe HJS 94626900 640306	<b>259,18 €</b>
Motorcraft	5M5J-5H221-B1A RPR-01/A KBA17029	<b>17,88 €</b>
Motorcraft	5S6J-5H221-A1A RPR-02/A KBA17030	<b>9,99 €</b>
Motorcraft	5S7J-5H221-C1A RPR-03/A1 KBA17047	<b>19,77 €</b>
Oberland Mang	KBA16790 OM2-EU2/4 865650 05011H	<b>21,34 €</b>
Oberland Mang	KBA17071 OM4 EU3 868700 021308	<b>19,05 €</b>
Oberland Mang	KBA17137 OM-PMS03-02 858.206	<b>65,66 €</b>
Oberland Mang	KBA17140 OM-PMS06-01	<b>34,68 €</b>
Oberland Mang	KBA17140 OM-PMS06-02	<b>75,32 €</b>
Oberland Mang	KBA16998 OM4-000306	<b>26,07 €</b>
Proventia	DOCA OT-110-001 10 14	<b>20,96 €</b>
Twin-Tec	D300 103R-000209	<b>16,72 €</b>
Twin-Tec	D320 KBA16814	<b>15,20 €</b>
Twin-Tec	RFK-TT-02 103R-000228 KBA16995	<b>15,49 €</b>
Twin-Tec	RFK-TT-08 103R-000262 KBA17011 Honda unte	<b>77,87 €</b>
Twin-Tec	RFK-TT-09/A PM1114-02 KBA17012	<b>29,18 €</b>
Twin-Tec	RFK-TT-15/A 103R-000289 KBA17033 BMW	<b>53,23 €</b>
Twin-Tec	RFK-TT-16/A 103R-000290 K700055	<b>55,50 €</b>
Twin-Tec	RFK-TT-16/C 103R-000323 KBA17034	<b>60,93 €</b>
Twin-Tec	RFK-TT-19/B KBA16999	<b>6,00 €</b>
Twin-Tec	TT-05 KBA16980 103R-000190	<b>16,23 €</b>
Aftermarket	Bosal 4Reihen Fächer Benzin	<b>7,44 €</b>
Aftermarket	KBA16993 KG-5E 82758 0312232 (GM50)	<b>29,68 €</b>
Aftermarket	LRT 7078 103R-000065 CP10	<b>1,82 €</b>
Aftermarket	TPCats 103R-0022820	<b>7,71 €</b>
Aftermarket	0408327 (baugleich GM23)	<b>7,04 €</b>